

**IF YOU HAVE TROUBLES
WITH
DEVICE FIRMWARE UPDATE**

Download the update

The screenshot shows the website header with contact information: LifeCell +380 73 415 62 31, AUTOKEY.COM.UA, and email CANALYZER1@GMAIL.COM. The main content area features a navigation menu on the left with links for HOME, SOFTWARE, HARDWARE, KNOWLEDGE, TUTORIAL, and FAQ. The central text reads 'MAC / MPC / SPC PROGRAMMER' and '200 USD'. Below this, it says 'NEW SOFTWARE / FIRMWARE' and provides a link for 'MACACA ver1.12 and firmware ver1.26'. A black arrow points from the text 'download this update' to the link.

LifeCell
+380 73 415 62 31

AUTOKEY.COM.UA
UKRAINE KIEV

mail
CANALYZER1@GMAIL.COM

HOME
SOFTWARE
HARDWARE
KNOWLEDGE
TUTORIAL
FAQ


**MAC / MPC / SPC
PROGRAMMER**

200 USD

NEW SOFTWARE / FIRMWARE
[MACACA ver1.12 and firmware ver1.26](#)

download this update

Try to update





u2j_firmware_v1.26.fwu
Файл "FWU"
35 КБ



macaca_v1.12.exe



Macaca_v1.12_fw_v1.26.rar
Файл "RAR"
301 КБ

Macaca Programmer - [COM142]

File Buffer Device Options Help

Device: Output voltage: Region:

Buffer size: n/a


Открыть

Папка:


Имя файла:

Тип файлов:

Error message




Update result





Enter device boot mode

Disconnect usb cable and short



Connect usb cable and try to update.





Close the program and disconnect usb cable

